



## Release 2.3 Maintenance Errata

---

- In the Features Overview and Marketing Flash document under PMS Enhancements, 'Support for Micros Fidelio Check in/Check out (CI/CO)' has been incorrectly stated as 'Support for Marriott Check in/Check out (CI/CO)'.
  - Readme document should include the following:
    - With 2.3 maintenance and 4.3 maintenance release the NSE moves to a single IP configuration which restricts the ports that can be used for static port mapping. No ports below 5000 can be used for static port mapping in the 2.3M and 4.3M release.
-